



# Addendum # 1



**Date:** May 21, 2026  
**To:** All bidders  
**From:** Louis Joseph, Buyer  
**Solicitation Number:** ITB# CDS/260655  
**Solicitation Title:** Residential Rehabilitation - Johnson

## SOLICITATION ADDITIONS, CLARIFICATIONS, AND CORRECTIONS

**NOTE: ALL INSTALLATIONS OR REPLACEMENTS MUST INCLUDE NEW PRODUCTS OR MATERIALS.**

### ITEM 8 – Interior Repairs

1. Install bifold closet doors in the hall closet. Opening is 48". Match other doors in texture/paint.
2. Reinstall 3-bedroom doors (slabs).
3. Replace the broken windowpane in the Living Room window. Pane should match other window glass.
4. Repair 6"-8" hole in LR wall above hall switch plate.
5. Replace flooring in the hall with a water-resistant LVP approx. 24s.f. Install transition strips. Repair the surrounding floor as needed to install the LVP.



Rehab Specialist  
May 20, 2026 10:37 AM